


# Long Span Timber Structures with Composite Action – from disaster to success

Nils Ivar Bovim  
Norway

# World's highest buildings and trees




Composite action is the only solution to increase the size of timber structures made from from small pieces of wood

- Opened about 1930
- «Barrel structure» made of short timber pieces with composite action



Nørreport Station, Copenhagen

# Bottom-up view of Barrel arch, Nørreport Station



Nørreport Station, Copenhagen

# Mühlacker transmission tower made of timber

In 1933-34, a 190 m high wooden tower was built - the tallest structure ever built !!

The radio tower was built for antennas with transmission power of 100 kW.

On April 6, 1945, the wooden tower and the masts carrying the system of T-antennas were blown up by the SS to prevent its capture by the Allies in World War II.




# World's biggest timber structure: Hangar for 8 airships

- Hangar for 8 airships built during 2. World War,
- Lack of steel during the war forced the use of timber in the hangars
- Span of structure: 115 m
- Length of structure: 340 m
- Height of structure: 52 m
- Contains  $\approx$  1 million board meter of fireproofed Douglas fir
- Held together by 79 tons of bolts and washers and 30 tons of ring connectors

## Several disasters:

- Twice in early 1943, gusty winds collapsed the partially built hangars
- One in Oregon was destroyed by fire
- **Fifteen other** airship hangars - only five of which survived - were built from the same design.



# Now Tillamook Air Museum, Oregon US




Picture from  
2. World War

# World's biggest timber structure: Hangar for 8 airships



# World's biggest timber structure: Hangar for 8 airships



# World's biggest ...: Detail of structure



# Generally, 3 main reasons for collapse of structures

1. Planning and design
2. Construction / building phase
3. Lack of maintenance, use and others


Reasons No.1 and 2 are of about the same order,  
No.3 relatively less.

About **60% of the failures occur during the building phase**. Even if the problem is planning or design, the failure often occur during the building phase.


Failures where people were **killed or injured** is relatively worse, **65-70% occurs during the building phase**.

# Probably the most spectacular timber structure in history

The building phase



Formwork and scaffolding for Sandö Bridge,  
Sweden 1938-39. Arch span 264 m, 11,1 m wide  
The highest scaffolding tower was 37 m.



# **The idea to Sandø bridge probably came from the France bridge Pont de Plougastel built 1926 – 1930**

3 reinforced concrete arch bridges, each with ~188 m span

The Plougastel Bridge, was built near Brest, France as hollow-box arch, made of reinforced concrete.



**The formwork was built with steel framework**



# Plougastel bridge

Formwork cladding of diagonal timber boards



# Pont de Plougastel (Finistère)

The formwork was reused for the 3 arches



## The structure:



Upper and lower chord is parallel nailed (12" nails) massiv wood structure with nailed diagonals in between. **Thickness of the chords is only 200 mm!**


**Not only the most spectacular timber structure, also the most spectacular transportation of such a structure**



Formwork and scaffolding were buildt on the riverbank


The scaffolding towers were removed an **the whole structure transported across the river with boats** at the 18th of May, 1939

# Probably the most spectacular timber structure in history



Picture taken just before landing one end of the timber arch

# Probably the most spectacular timber structure in history



The operation was a success and casting of the concrete arch could start.

# Probably the most spectacular timber structure in history



30. August, 1939 - only 12 m from finishing the concrete casting (!) - a huge sound was heard and the complete structure collapsed

# Probably the most spectacular timber structure in history

About 40 workers followed the bridge into the water -

**18 died**

Next day 2nd world war started, leaving one of the biggest work accidents i Sweden as a short note in the newspapers.


Witness descriptions indicated **buckling in vertical direction (in plane) of the whole section as the failure mode.**

The investigating committee stated that the failure was caused by insufficient strength/stiffness of the transverse bracing between the two flanges.

Later investigations have proposed lateral instability of the arch as responsible for the failure



**The Sandö Bridge was completed and opened in 1943 using a new scaffolding system with poles through the riverbed.**



**The Sandö Bridge was completed and opened in 1943.  
The worlds longest spanning concrete arch bridge until 1964**



# The Sandö Bridge was completed and opened in 1943.

From Wikipedia, about bridge failures and Sandö bridge:

|                              |                                        |        |                |                      |                               |           |                                |                                                                                                                                                                               |
|------------------------------|----------------------------------------|--------|----------------|----------------------|-------------------------------|-----------|--------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">Sandö Bridge</a> | <a href="#">Kramfors, Ångermanland</a> | Sweden | 31 August 1939 | Concrete arch bridge | Collapsed during construction | 18 killed | Complete loss of the main span | Did not receive much media attention as the Second World War began the next day. The bridge was finished in 1943 as the longest concrete arch bridge in the world until 1964. |
|------------------------------|----------------------------------------|--------|----------------|----------------------|-------------------------------|-----------|--------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

Learning from failures are especially of interest for new generations of engineers and for development of new and better bridge design, and even for development of timber structures in general!

However, nobody has concluded what caused the failure of Sandö formwork in reality.

# Instability of timber structures is a real problem – as for other materials

Instability is a very dominant failure mode according to a comprehensive Swedish/Finnish report from Lund University, 2007

Collaps or failure was caused by insufficient or absent bracing leading to buckling and material failure

| Failure mode                           | Percentage |
|----------------------------------------|------------|
| Instability                            | 30         |
| Bending failure                        | 15         |
| Tension failure perpendicular to grain | 11         |
| Shear failure                          | 9          |
| Drying cracks                          | 9          |
| Excessive deflection                   | 7          |
| Tension failure                        | 5          |
| Corrosion of fasteners / decay         | 4          |
| Withdrawal of fasteners                | 3          |
| Compression                            | 2          |
| Other / unknown                        | 21         |



# Stability failure - lack of bracing



Photo taken about 10 seconds before the 52' scissor trusses collapsed. There was no wind or snow loads, only dead load from the trusses! The top chord is buckling from a lack of proper top chord bracing

# Challenges for scissor trusses

Compared with trusses having horizontal ceiling

- the structural height of scissor trusses are less (for identical roof pitch)
- the axial forces in upper and lower chord are significantly higher and lateral bracing of the chord even more important
- the center of gravity is significantly higher positioned, resulting in higher erection forces and need for more extensive bracing during construction
- horizontal forces in the supports tend to **push the supports outwards**



Kingpost



Double Fink



Queenpost



Double Howe



Fink



Hip



Howe




Scissors

# Example Oslo Cathedral (1694 -)

- Vaulted ceiling and scissor trusses
- The bracing system was cut (!) because a new organ demanded more space


Sperrebind



# Oslo Cathedral (1694 -)

- Vaulted ceiling and scissor trusses
- The bracing system was cut (!) because a new organ demanded more space
- Horizontal reaction forces tend to push external walls outwards (70 mm)

Sperrebind



# Lack of stability in the construction phase



**Only a minor part  
of the bracing system  
was mounted!**



**It seems too  
late to install this  
stabilizing boards!**



**Here we have the rest of  
stabilizing sheathing!**

## Short purlins – weak nailed joint on every truss



# **Lett-Tak roof panel system with composite action of plywood, timber and steel**


- **Located in Larvik, Norway**
- **Yearly production capacity 300 000 m<sup>2</sup>**
- **Advanced product, full control from production to finished roof**
- **Several projects also in Sweden, Denmark, Iceland, Germany**
- **Dead weight 0,4 - 0,5 kN/m<sup>2</sup>**
- **Insulation: U-values from 0,18 – 0,07 [W/m<sup>2</sup>K]**
- **Fire resistance up to 90 min.**
- **Max span width 18 m**

All mounting and fixing work is done from above




# Cutaway illustration of Lett-Tak roof panel

- Composite-element, SINTEF TG-2215, ETA under preparation
- Roof panel width 2,4 m and max length 18 m
- 2 steel profiles, height from 130 up to 440 mm, thickness 1,0 to 2,0 mm
- Timber flanges 48x71, 48x96 or 48x121 mm glued or nailed to steel
- Finnish plywood, 15 mm, 18 or 21 mm thickness glued to timber flanges




# Fire resistance Lett-Tak roof panels


Brannmotstand REI-15




Brannmotstand REI-60



Brannmotstand REI-30



Brannmotstand REI-90



\*) Rockwool Building 90, EN 13162 density min. 90 kg/m<sup>3</sup>,  $\lambda_D = 0,034$  W/mK

**Fire resistance given for fire from underneath or from upperside,  
ref. ETA**

# Full scale test, 10 m Lett-Tak roof panels at the Norwegian Building Research Institute for European Technical Approval (ETA) 2015




# From the full scale test of four Lett-Tak roof panels



# Full scale test 4 stk 10 m Lett-Tak panels 14.1.2015

Test element 1, 2, 4 og 5 bruddlast og senterdeformasjon




# Screws in diaphragm structures

- Some screws shows brittle failures, before bending!
- Always bend some screws by hand to confirm the ductility!
- Bending to  $20\text{-}25^\circ$  before failure is ok !



# Design tools – Lett-Tak

**Tekla for BIM design of the projects with proprietary modul for Lett-Tak roof panels**





From 5 up to 9 trusses were collected in bundles to increase the fire resistance of the nailplate trusses.  
Lett-Tak roof panels were fixed to bundles of trusses.  
(Location Gran, Hadeland, Norway 2013)




**9 trusses collected  
in one bundle**

**Lett-Tak  
roof panels**




Timber diagonals in walls  
are leading forces down to  
the foundation






Norwegian project with bundled timber trusses in combination with Lett-Tak panels, 2013

The Lett-Tak system also gives the possibility for diaphragm action of the roof. The roof panels are taking care of the **shear flow** in the diaphragm. elementer




# Axial forces in screws from shear flow $F_H$

$$D_1 = \frac{6 \cdot M \cdot (n-1)}{450 \cdot n \cdot (2n-1)} = \frac{F_H \cdot H_y \cdot (n-1)}{75 \cdot n \cdot (2n-1)}$$



$D_1$  – forces comes in addition to lifting forces from suction on the roof and internal air pressure



# Detail of connection to longitudinal wall





Fig. 3

Prinsipp for utførelse av tilslutning mot yttervegg. Det er forutsatt at vegg er reist før montasjen av takelementene.

# Telenor Arena – Football and event hall

Covered and stabilized with Lett-Tak roof elements



# Telenor Arena

## Mounting the first Lett-Tak roof element



# Telenor Arena – Football and event hall

Covered and stabilized with Lett-Tak roof elements



# Telenor Arena – Football and event hall

Covered and stabilized with Lett-Tak roof elements



# Swedbank Arena, Stockholm – Lett-Tak roof panels

Juli 2011



# Swedbank Arena, Stockholm – Lett-Tak roof panels



# Swedbank Arena, Stockholm – Lett-Tak roof panels



# Torvehaller – in the centre of Copenhagen



A relatively soft (and weak) steel structure.

Stabilizing the whole buildings is an important function of the Lett-Tak roof panels in this project.

# Torvehaller – in the centre of Copenhagen



# Gardermoen airport – Lett-tak roof panels all over



# **New inland terminal – Gardermoen airport 2014**

## **Main structure of Glulam, covered and stabilized with Lett-Tak roof panels**



# Gardermoen Pir North 2014

- The roof panels in some part of the roof had to be twisted (double curved shape)  
Picture from the factory, testing twisting of roof panels
- Even if the panel is soft in the transverse direction, twisting up to  $10^\circ$  of 9 m long roof panels could be a challenge. Some steel end plates had to be skewed!



# Gardermoen airport – Pir North 2015

